

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 24505 Stonehouse Rise

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 26 Mar 2024 26 Mar 2027 36 3 year Re-Assessment Type 1 (Common Parts Only - Non Destructive) Gary Bredin

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

Stonehouse Rise Asset ID: 24505

The Scheme

Scheme Name	Stonehouse Rise
Scheme Address	Stonehouse Rise
Postcode	GU16 8DP
Region	South
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Surrey Fire and Rescue
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	Garage and Car Parking Bays (S45), General Needs (S30), Peerless General Needs - LSVT (S29)
Build Date	Jan 1 1971
Number Of Homes	72
Homes breakdown	Garage, Flat, House, Bungalow
External wall construction	Facing Brick
External wall finish	Facing Brick, Timber Clad
Roof construction	Concrete, Concrete, Timber, Timber
Roof covering	Flat Roof, Interlocking Pitched, Plain Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	One Unprotected
Number of External Staircases	None
External Balcony part of escape route?	N/A
Unusual features	
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

MIS-AMS ActiveH - Fire Risk Assessment Report

Asset ID: 24505

Stonehouse Rise

Fire Detection and Warning System	Flats only
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	80
Occupant tenure type breakdown	Garage and Car Parking Bays, General Needs, Leasehold

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	11
Overdue Annual Emergency Lighting tests	11
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	
Building Fire Safety Surveys - Communal Doors	

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment
FRA Frequency (Months)
Purpose of Fire Risk Assessment
Type of Risk Assessment
Quantity
Fire & Safety Assessor
Enforcing Fire Authority
Scheme Tel. No
Other staff in attendance
Number of on-site Accent staff
Number of other (non-Accent) staff
Scheme Inspection completed
Number of occupants
Personal Emergency Evacuation Plans in place
Current Evacuation Strategy
Conversion or purpose-built
Number of Storeys
Number of floors on which car parking is provided
Is there a habitable basement?
No. of internal staircases (protected/unprotected)
Number of external staircases
External balcony part of escape route?
Unusual features



26/03/2024
36
3 year Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
Gary Bredin
Surrey Fire and Rescue
None
None
Contract Cleaners in common areas
Yes
80
Yes
Stay Put (Delayed) Evacuation
Purpose Built
2
0
No
One Unprotected
None
N/A

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats only
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage? Comment	Yes
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats) Comment	Yes
Electrical App/PA Testing - tested within past 12 months?	N/A
Comment	
Absence of trailing leads and adapters?	Yes
Comment	
Evidence that mobility scooters are not being stored/charged in common areas?	No
Comment	
Is there a purpose built mobility scooter store/charging area?	N/A

Comment

Does the building have a lightning protection system? No
Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	
Valid LGSR held on file for fixed communal area gas appliances? (Boilers)	N/A
Comment	
Valid LGSR held on file for residential flats that contains gas appliances?	Yes
Comment	
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment	Yes
Are unnecessary accumulations of combustible materials or waste avoided?	No
Comment	Items are being stored outside flat 5 and 12. Housing partner dealing.
Are combustible materials and substances separated from ignition sources and stored appropriately?	Yes

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

Observation	Priority	Referred To	Required By:	Task ID
Blocks 3-6 and 11-14. Items are being stored within the	Internal - Medium	Housing Partner		

N/A

Blocks 3-6 and 11-14. Items are being stored within the means of escape. All items in these areas need to be removed.



Observation P	Priority	Referred To	Required By:	Task ID
Fly tipping inside and out of blocks 33-36 In	nternal - Medium	Housing Partner		

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?	No
Comment	

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	No
Comment	Fire stopping is required in every electrical intake cupboard. Job raised.
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? Comment	Yes
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment	N/A
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment	Yes
Loft hatches fire resisting?	Yes
Comment	
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment	Yes
Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment	Yes
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment	N/A
Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment	N/A
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	

Records of monthly/annual testing available?

Comment

Yes

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	No
Comment	
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	

Observation	Priority	Referred To	Required By: Task ID

Fire safety notices are posted throughout all blocks.



Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?		N/A
Comment		
Is fire detection and warning system appropriate for occu risk, as per BS 5839-1:2017? Comment	pancy and fire	Yes
Is the fire detection and warning system maintained/teste certificates saved on file?	ed and all	Yes
Comment		
Fire alarm components in good condition and securely fix walls/ceilings?	ked to	Yes
Comment		
Hold open devices operate at the sounding of the alarm a serviceable condition?	and are in a	N/A
Comment		
Are there heat detectors located in the Kitchen, Boiler, P Laundry?	ant Room and	N/A
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 9 of 14	Generated 26/03/2024 16:02:43

Comment

Is the fire alarm panel remotely monitored, and if so are there records of N/A regular testing? Comment

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations	No
provided at this scheme?	
Comment	

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	No
Comment	
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	Yes
Have all details required by regulations been shared with all other Responsible Persons?	
Comment	
Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?	Yes
Comment	
Will this FRA be shared will all other Responsible Persons for the premises?	Yes
Comment	
How will this sharing be achieved?	All details loaded onto
Is an office or IL scheme being inspected?	N/A
Comment	
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?	N/A
Comment	
Offices - Are there suitable arrangements for ensuring the premises are evacuated?	N/A
Comment	
Offices - Are there suitable arrangements for evacuating disabled people?	N/A
Comment	
Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?	N/A
Comment	

M files.

Offices/IL Schemes - Is there a suitable assembly point?		
Comment		
Offices - Are fire drills carried out at appropriate intervals?	N/A	
Comment		

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Premises Inspection Box

Is there a premises information box for fire & rescue service use?	N/A
Comment	
Are there arrangements to check the premises information box is kept up to date?	
Comment	

Evacuation Policy

Are there suitable arrangements for summoning the fire service?	Yes
Comment	It is the responsibility of the customers to call the emergency services.
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	
Engagement with Residents	
Has information of fire procedures been disseminated to residents?	Yes

No

Comment
Is general fire safety information disseminated to residents?
Comment
This is posted on the information boards in every block.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	MEDIUM	Х	HIGH		
-----	--------	---	------	--	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 24505

Stonehouse Rise

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Moderate	