

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 62 De Havilland Court De Havilland Road, Wisbech

Cover Sheet

Photo



Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor 09 Aug 2023 09 Aug 2026 36 3 year Re-Assessment Type 3 (Common Parts and Flats - Non Destructive) Lynn.betteridge@accentgroup.org

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

Asset ID: 62

The Scheme

Scheme Name	De Havilland Court
Scheme Address	De Havilland Court De Havilland Road, Wisbech
Postcode	PE13 3AL
Region	East
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Cambridgeshire Fire and Rescue Service
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	CAT1 Housing for Older People (S27), Supported Housing (S50)
Build Date	Jan 1 1991
Number Of Homes	18
Homes breakdown	Flat
External wall construction	Facing Brick
External wall finish	Facing Brick, Timber Clad
Roof construction	Timber
Roof covering	Interlocking Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	2 This scheme has all its doors open to safe Air.
Number of External Staircases	None
External Balcony part of escape route?	Yes
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

De Havilland Court De Havilland Road, Wisbech

Fire Detection and Warning System	Flats and common areas linked
Grade of fire alarm	Grade B
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Asset ID: 62

Number of occupants	18
Occupant tenure type breakdown	General Needs, CAT1 Housing for Older People, Designated Supported Housing for Older People

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	1
Overdue Annual Emergency Lighting tests	2
Overdue Weekly Fire Alarm Testing	1
Overdue Fire Panel - Six Monthly Testing	1
Overdue Fire Safety Equipment tests	

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	12

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

De Havilland Court De Havilland Road, Wisbech Asset ID: 62

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment	09/08/2023
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year Re-Assessment
Type of Risk Assessment	Type 3 (Common Parts and Flats - Non Destructive)
Quantity	1
Fire & Safety Assessor	Lynn.betteridge@accentgroup.org
Enforcing Fire Authority	Cambridgeshire Fire and Rescue Service
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	18
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of Storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	2 This scheme has all its doors open to safe Air.
Number of external staircases	None
External balcony part of escape route?	Yes
Unusual features	None



98)

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Residential
Fire Detection and Warning System	Flats and common areas linked
Grade of Fire Alarm	Grade B
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?	Yes
Comment	All equipment secure and intact on the day of inspection.
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	Electrical condition report dated as18/12/18 due this December for re certification.
Electrical App/PA Testing - tested within past 12 months?	No
Comment	
Absence of trailing leads and adapters?	N/A
Comment	
Evidence that mobility scooters are not being stored/charged in common areas?	Yes
Comment	Resident charging in open area outside flat insafe Air, charger PAT tested on request.

Asset ID: 62 De Havilland Court De Havilland Road, Wisbech

Is there a purpose built mobility scooter store/charging area?	No
Comment	
Does the building have a lightning protection system?	No
Comment	

Gas installations

Is there a commercial/domestic gas supply to the scheme?	No
Comment	

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	Secure metal access and egress.
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	
Are unnecessary accumulations of combustible materials or waste avoided?	Yes
Comment	
Are combustible materials and substances separated from ignition sources and stored appropriately?	N/A
Comment	
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	N/A
Comment	

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Yes

Comment

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	All flat doors open to safe air on ground floor,this is the same at first floor level residents can either go right or left as there is 2 staircases with protection.
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	All flat doors open to fresh Air.
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment	
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment	N/A
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	Yes
Comment	In residents flats.
Comment Loft hatches fire resisting?	In residents flats. N/A
Loft hatches fire resisting?	

MIS-AMS ActiveH - Fire Risk Assessment Report

Asset ID: 62 De Havilland Court De Havilland Road, Wisbech			
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	N/A		
Comment			
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A		
Comment			
Emergency Escape Lighting			
Is the emergency lighting correctly specified and installed as per current standards?	Yes		
Comment	Tested by Tunstalls contractor.		
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes		
Comment	In good condition at the time of inspection.		
Records of monthly/annual testing available?	Yes		

Comment

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes

The emergency lighting system at this scheme has been tested monthly on 24/7/23 and the annual drop

test was completed on 24/7/2023.

De Havilland Court De Havilland Road, Wisbech

Comment	System is tested 6 monthly and fire alarm test 11/7/23
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	N/A
Comment	
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	Yes
Comment	
Fire Extinguishing Equipment	
Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	No

Comment

Asset ID: 62

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	Yes
Comment	Communication with all parties within the Accent Housing Association.
Will this FRA be shared will all Accountable Persons for the premises?	Yes
Comment	Data sharing via active H.
How will this sharing be achieved?	
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	Yes
Have all details required by regulations been shared with all other Responsible Persons?	Yes
Comment	
Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?	Yes
Comment	Scheme manager and onactive H.
Will this FRA be shared will all other Responsible Persons for the premises?	Yes
Comment	All recorded on active H database.

De Havilland Court De Havilland Road, Wisbech

How will this sharing be achieved?	The fire risk assessment for the building will be held on active H if residents or any other person's wish to look at the FRA the details will be shared and communicated on request.
Is an office or IL scheme being inspected?	No
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	

Evacuation Policy

Asset ID: 62

Are there suitable arrangements for	or summoning	the fire	service?
-------------------------------------	--------------	----------	----------

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance? Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?	Yes
Comment	When the residents take ownership of their flat they're given fire safety advice and also leaflets and a link into the website to look at the FRA
Is general fire safety information disseminated to residents?	Yes
Comment	Fire safety notices are displayed in the communal areas. The residents are able to access a website.
FRA Frequency	

Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment

Yes

Yes

Yes

report a fire.

The residents call the fire and rescue service to

Asset ID: 62 De Havilland Court De Havilland Road, Wisbech

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	No
Are there fire related remedial works required at this property, that will affect the fabric of the building?	No
Comment	
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	нідн	
-----	---	--------	------	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	
			ORTIONE	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Asset ID: 62

De Havilland Court De Havilland Road, Wisbech

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial