

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 32954 **St Catherines, Bradford**

Cover Sheet

Photo



Date of Fire Risk Assessment	13 Oct 2023
Date of Next Fire Risk Assessment	13 Oct 2026
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year Re-Assessment
Type of Fire Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Fire & Safety Assessor	Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	St Catherines
Scheme Address	St Catherines, Bradford
Postcode	
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	General Needs (S30)
Build Date	Jul 22 2014
Number Of Homes	20
Homes breakdown	Flat, House
External wall construction	Natural Stone
External wall finish	Artificial/Natural Stone, Facing Brick
Roof construction	Timber
Roof covering	Flat Roof, Plain Pitched, Slate Pitched
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Conversion
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	One protected
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicle Access to one or more elevations

Asset ID: 32954 St Catherines, Bradford

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade D
Category of fire alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers supplied/fitted	No
Fixed Fire Fighting Installations	No

Customers

Number of occupants	30
Occupant tenure type breakdown	General Needs

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	2
Overdue Annual Emergency Lighting tests	2
Overdue Weekly Fire Alarm Testing	2
Overdue Fire Panel - Six Monthly Testing	2
Overdue Fire Safety Equipment tests	2

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment	13/10/2023
FRA Frequency (Months)	36
Purpose of Fire Risk Assessment	3 year Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Quantity	1
Fire & Safety Assessor	Steven Manners
Enforcing Fire Authority	West Yorkshire
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	None
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	30
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Conversion
Number of Storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	One protected
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade D
Category of Fire Alarm	LD3 Minimum Protection
Emergency Lighting Provision	Non Maintained System - Common Areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	No
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	No
Fire Blanket(s) present	No
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	Yes

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?	Yes
Comment	All in good condition at the time of inspection
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	All records are available on ActiveH
Electrical App/PA Testing - tested within past 12 months?	N/A
Comment	Not required
Absence of trailing leads and adapters?	N/A
Comment	None found
Evidence that mobility scooters are not being stored/charged in common areas?	Yes
Comment	None on scheme
Is there a purpose built mobility scooter store/charging area?	No

Comment Not required

Does the building have a lightning protection system? No

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? Yes

Comment

Valid LGSR held on file for fixed communal area gas appliances?
(Boilers) Yes

Comment All records are available on ActiveH

Valid LGSR held on file for residential flats that contains gas
appliances? Yes

Comment All records are available on ActiveH

Are smoke/heat detectors within General Needs flats subject to an
annual inspection and the results Yes

Comment Yes, checked by contractor at the same time as
gas and CO

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered
to? Yes

Comment No smoking allowed in the communal areas

Adequate security against arson? Yes

Comment Buzz in fob system to enter the building

Are refuse/recycling bin areas managed and suitably located? Yes

Comment Stored away from the building

Are there communal cooking facilities at this scheme? No

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general
waste, contractors waste and residents personal items? Yes

Comment All clear at the time of inspection

Are unnecessary accumulations of combustible materials or waste
avoided? Yes

Comment None found at the time of inspection

Are combustible materials and substances separated from ignition
sources and stored appropriately? Yes

Comment	None found at the time of inspection
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	N/A
Comment	Not allowed in the communal areas

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?	Yes
Comment	Nothing found at the time of inspection

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
Comment	
Escape routes unobstructed and safe to use?	Yes
Comment	All clear at the time of inspection
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes
Comment	All travel distance is within the guidelines
Escape routes lead to final exits and open in direction of escape where necessary?	Yes
Comment	

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment	All good at time of inspection
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A
Comment	None fitted
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	Yes
Comment	Small roof void in block 8 to 15, roof void within flat 5
Loft hatches fire resisting?	Yes

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

N/A

Comment

No cross in doors

Do external walls, doors, windows and anything attached to the exterior, limit fire spread?

Yes

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Yes

Comment

Tested by Tunstall and all records are available on ActiveH

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

N/A

Comment

None fitted

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Yes

Comment

Emergency lighting units in good condition and securely fixed to walls/ceilings?

Yes

Comment

All in good condition at the time of inspection

Records of monthly/annual testing available?

Yes

Comment

All records are available on ActiveH

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Yes

Comment

Notices are displayed throughout the building

Directional fire escape signage in place and adequate?

Yes

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

N/A

Comment

No lift at this scheme

Do common area fire doors display the correct signage on both sides where applicable?

Yes

Comment

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	Maintained by Tunstall and all records are available on ActiveH
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in good condition at the time of inspection
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	None fitted
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	N/A
Comment	
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	No
Comment	Not monitored but tested weekly by Tunstall and recorded on ActiveH

Observation	Priority	Referred To	Required By:	Task ID
--------------------	-----------------	--------------------	---------------------	----------------

Fire Panel and AOV Control flats 8 to 15



Observation	Priority	Referred To	Required By:	Task ID
--------------------	-----------------	--------------------	---------------------	----------------

Fire panel and AOV Control flats 5 to 7



Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

No

Comment

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Yes

Comment

Will this FRA be shared with all Accountable Persons for the premises?

Yes

Comment

Available on ActiveH

How will this sharing be achieved?

As above

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

No

How will this sharing be achieved?

Is an office or IL scheme being inspected?

No

Comment

Passenger Lift

Is the scheme fitted with a passenger lift?

No

Comment

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

No

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Yes

Comment

All residents are instructed to contact the fire service by dialing 999

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Yes

Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment

On induction by leaflets and on the website

Is general fire safety information disseminated to residents?

Yes

Comment

As above and action notices are displayed throughout the building

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

No

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR MAJOR CRITICAL

The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is: **Trivial**