Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 54 Walpole Court, Peterborough

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

20 Apr 2023

31 Jul 2023

36

3 year Re-Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Lynn Betteridge accent fire safety

I	nıs	report	has	been	val	ıda	ted	by:
---	-----	--------	-----	------	-----	-----	-----	-----

Name:

Date:

Comment:

The Scheme

Scheme Name Walpole Court

Scheme Address Walpole Court, Peterborough

Postcode PE1 2HF

Region East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

The Building

Accommodation Type CAT1 Housing for Older People (S27), Supported

Housing (S50)

Build Date Jan 1 1987

Number Of Homes 16

Homes breakdown Flat

External wall construction Timber Frame

External wall finish Facing Brick, Timber Clad

Roof construction Timber

Roof covering Slate Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

No communal areas just outside washer dryer

storag

Number of External Staircases None

External Balcony part of escape route?

N/A

Unusual features Washer dryer outhouse

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 54 Walpole Court, Peterborough				
Fire Detection and Warning System	Common areas only			
Grade of fire alarm	Grade E			
Category of fire alarm	LD3 Minimum Protection			
Emergency Lighting Provision	Not fitted			
Portable Fire Extinguishers supplied/fitted	No			
Fixed Fire Fighting Installations	No			
Customers				
Number of occupants	20			
Occupant tenure type breakdown	General Needs, CAT1 Housing for Older People, Designated Supported Housing for Older People			
Fire Safety Related Customer Safety Servicing				
Overdue communal gas safety checks	0			
Overdue domestic gas safety checks	0			
Overdue communal electrical condition checks	0			
Overdue domestic electrical condition checks	0			
Overdue alarm call pull chord tests	0			
Overdue communal PAT testing	0			
Overdue customer mobility scooter PAT testing	0			
Overdue Monthly Emergency Lighting Switch Tests				
Overdue Annual Emergency Lighting tests				
Overdue Weekly Fire Alarm Testing	0			
Overdue Fire Panel - Six Monthly Testing				
Overdue Fire Safety Equipment tests				
Building Fire Safety Surveys - Communal Doors				
Failing Communal Fire Doors	0			
Communal Fire doors due for replacement within 5 years	0			
, - ,				
Dwelling Doors				
Failing Dwelling Fire Doors	0			
Dwelling Fire doors due for replacement within 5 years	0			

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 20/04/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 3 (Common Parts and Flats - Non Destructive)

Quantity

Fire & Safety Assessor Lynn Betteridge accent fire safety

Enforcing Fire Authority Cambridgeshire Fire and Rescue Service

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

Scheme Inspection completed Yes

Number of occupants 20

Personal Emergency Evacuation Plans in place Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

No communal areas just outside washer dryer

storag

Number of external staircases None

External balcony part of escape route?

N/A

Unusual features Washer dryer outhouse

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Common areas only

Grade of Fire Alarm Grade E

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Not fitted

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Washer dryer external to scheme

Electrical App/PA Testing - tested within past 12 months?

Yes

Comment

Absence of trailing leads and adapters? Yes

Comment

Comment

Evidence that mobility scooters are not being stored/charged in N/A

common areas?

Is there a purpose built mobility scooter store/charging area?

N/A

Yes

No

Asset ID: 54 Walpole Court, Peterborough	
Comment	
Does the building have a lightning protection system?	No
Comment	
Gas installations	
Is there a commercial/domestic gas supply to the scheme?	N/A
Comment	
Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment	N/A
Valid LGSR held on file for residential flats that contains gas	N/A
appliances? Comment	
Are smoke/heat detectors within General Needs flats subject to an	N/A
annual inspection and the results	
Comment	
Other Sources of Ignition	
Is there a no smoking policy in place, which is enforced and adhered to?	N/A
Comment	
Adequate security against arson?	Yes
Comment	
Are refuse/recycling bin areas managed and suitably located?	N/A
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	
Housekeeping	
Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment	N/A
Are unnecessary accumulations of combustible materials or waste avoided?	N/A
Comment	
Are combustible materials and substances separated from ignition sources and stored appropriately?	N/A
Comment	

Page 6 of 12

MIS-AMS ActiveH - Fire Risk Assessment Report

Generated 20/04/2023 11:23:44

Asset ID: 54	Walpole Court, Peterborough	
Furniture/furnishings in good of comply with modern standards Comment	condition, fire retardant/resistant and s and regulations?	N/A
Other Significant Fire	Hazards	
Are all other significant fire ha	zards adequately controlled?	Yes
Comment		
Means of Escape from	n Fire	
Is it considered that the buildir escape in case of fire?	ng is provided with reasonable means of	Yes
Comment		Purpose built washer dryer brick construction all flats have there own door.
Escape routes unobstructed a	and safe to use?	Yes
Comment		
Exits immediately openable w correctly?	ithout a key and/or failsafe's function	N/A
Comment		
direction of travel?	el where there is a single/alternative	Yes
Comment		V
Escape routes lead to final exinecessary? Comment	its and open in direction of escape where	Yes
Fire Spread and Devel	lopment	
Is it considered that the compa	artmentation is of a reasonable standard?	N/A
Comment		
Is there reasonable limitation of spread (walls, floors, ceilings) Comment	of surface finishes that might promote fire ?	Yes
-	vided in ducts/refuse chutes to protect smoke and combustion products?	N/A
	scertained, is the compartmentation ctory standard?	N/A
Comment	•	
Loft hatches fire resisting?		N/A
Comment		

Asset ID: 54 Walpole Court, Peterborough			
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment	N/A		
Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment	Yes		
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment	N/A		
Are roller shutter doors that are required to be FR, fire resisting and self-closing? Comment			
Emergency Escape Lighting			
Is the emergency lighting correctly specified and installed as per current standards? Comment	N/A		
Emergency lighting units in good condition and securely fixed to walls/ceilings? Comment			
Records of monthly/annual testing available?	N/A		
Comment			
Fire Safety Signs and Notices			
Are the correct Fire Action/Advice notices displayed in prominent	Yes		
locations within the common areas? Comment	Over door illuminated exit sign		
Directional fire escape signage in place and adequate?	N/A		
Comment			
Is there suitable LIFT signage i.e. do not use in case of fire?	No		
Comment			
Do common area fire doors display the correct signage on both sides N/A where applicable?			
Comment			
Means of giving Warning in case of Fire			

Comment

Is the scheme fitted with a communal area fire alarm?

No

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?

Comment

No

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Will this FRA be shared will all Accountable Persons for the premises?

Comment

How will this sharing be achieved?

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

Have all details required by regulations been shared with all other Responsible Persons?

Comment

Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?

Comment

Will this FRA be shared will all other Responsible Persons for the

premises?

Comment

How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Yes

Yes

Communication

Yes

Yes

Yes

No

Communication

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

No

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

No

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Yes

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Yes

Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment

Is general fire safety information disseminated to residents?

Yes

Comment

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

No

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised with our contractors.

Some minor works were required which have been raised with our contractors.

Unauthorised items were found in communal areas and arrangements were made for their removal.

Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW MEDIUM HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>